

Photo	Description	Number Of items	Name of item	م
U P COLUMN	Can measure power	6	3-PH Digital power	1
2 4 6 8 10 N 10	Power measurement	6	3 phase electronic wattmeter	2
2307 - 201 -	Transform voltage and current	6	Single phase transformer	3
13 23 20 13 13 13 13 13 13 13 13 13 13 13 13 13	Induction machine wound rotor	6	Induction machine Woundrotor	4



107 107 107 107 107 107 107 107 107 107	Three phase Transformer	3	Three phase Transformer	5
W7 O LIZ O V7 O LIZ VZ WZ	Induction machine squirrel cage rotor	6	Induction machine squirrel cage rotor	_6_
	Resistive Load	6	Resistive Load	7



\$2 00 100	Inductive load	6	Inductive load	8
111 122 123 1241 1241 1241 1241 1241 124	Resistive Load	3	Resistive Load	9
	Prime mover	06	Prime mover	10



Power supply DC an AC	03	Power supply DC an AC	11
DCmachine DCmachine	03	DCmachine	12